

ABSTRACT

A method for setting a clearance (G) between a sliding member (36) and a guide member (30) may includes the steps of determining the clearance (G), changing the clearance by utilizing a working means, and stopping the working means when the determined clearance (G) reaches a predetermined target clearance (Gt).